

2. You are performing a dependent resurvey in T. 4 N., R. 3 E., sec. 35 (Robie Creek area) and are subdividing the section. Due to a 1908 completion survey in this portion of the township, it appears that the 1/4 sec. cor. on the W. bdy. of the sec. would be offset from the 1/4 sec. cor. on the E. bdy. of sec. 34. However, the 1962 BLM remonumentation marked the brass cap as common corner (see below).

**T. 4 N., R. 3 E., “1/4 section corner, sections 34 and 35”. BLM 1962 Remonumentation.**



How would you resolve this situation (i.e. is this a corner common to both sections, as marked by the BLM in 1962 or is it an offset corner)?