

3. You are performing a dependent resurvey in T. 4 N., R. 6 E., sec. 24 (Twin Springs area), including restoring the meanders of the right bank of the Boise River. There seems to be a problem with the Compass Rule adjustment of the record meanders, with a misclosure/error of over 7 chs. in the NW part of the section. How would you resolve this situation?

